Seams Issues Matrix

Description of Seam Issue	Seam Interface Type	Region 1	Region 2	Seam Impediment Type	Currently Being Addressed ?	Comments
Non Standard Time Zone	All	All	All	Market Rule / Business Practice	No	The lack of a standard Time Zone causes Market Inefficiencies
MaxGen/MaxLoad 345Kv	Other	ECAR	ECAR	Physical	No	Undersized Transmission Line