Seams Issues Matrix

Description of Seam Issue	Seam Interface Type	Region 1	Region 2	Seam Impediment Type	Currently Being Addressed ?	Submitter	Reference Papers	Comments
Non Standard Time Zone	All	All	All	Market Rule / Business Practice	No	Phil Cox	No	The lack of a standard Time Zone causes Market Inefficiencies
MaxGen/MaxLoad 345Kv	Other	ECAR	ECAR	Physical	No	Phil Cox	No	Undersized Transmission Line
Definition & treatment of Firm/nonfirm Power	All	All	All	Market Rule / Business Practice	No	Lou Oberski	No	Annual Plan Item 4ci moved from MOS
Definition & treatment of Firm/nonfirm Transmission	All	All	All	Market Rule / Business Practice	No	Lou Oberski	No	Annual Plan Item 4cii moved from MOS
Provision of reserves across multiple control areas	All	All	All	Market Rule / Business Practice	No	Lou Oberski	No	Annual Plan Item 4cii moved from MOS